

Location Name: Craig 8-1 Location ID/API #: 309619



Location Name: Craig 8-1 Location ID/API #: 309619



Location Name: Craig 8-1 Location ID/API #: 309619



11/3/21 15:53
38.85939N 103.49996W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Craig 8-1 Location ID/API #: 309619



11/3/21 15:53
38.85938N 103.49993W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Craig 8-1 Location ID/API #: 309619



11/3/21 15:54
38.85938N 103.49992W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Craig 8-1 Location ID/API #: 309619



11/3/21 15:55
38.85946N 103.50033W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Inadequate containment around tank battery. Gap between
containment wall and ground on corner of tank battery**

Location Name: Craig 8-1 Location ID/API #: 309619



11/3/21 15:55
38.85953N 103.50030W

Location Name: Craig 8-1 Location ID/API #: 309619



11/3/21 15:55
38.85954N 103.50029W

Location Name: Craig 8-1 Location ID/API #: 309619



11/3/21 15:56
38.85948N 103.50030W

Location Name: Craig 8-1 Location ID/API #: 309619



11/3/21 15:59
38.85970N 103.50000W

Location Name: Craig 8-1 Location ID/API #: 309619



11/3/21 15:59
38.85980N 103.50006W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Craig 8-1 Location ID/API #: 309619



Stained soil inside containment where treater was located.