

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2021

Submitted Date:

11/05/2021

Document Number:

690102683

FIELD INSPECTION FORM

Loc ID 416873 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogccinspections@gwogco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416866	WELL	PR	03/19/2019	OW	123-31497	HCW 24-23	PA
416871	WELL	PR	03/01/2019	GW	123-31500	HCW 24-13	PA
416872	WELL	TA	03/30/2020	OW	123-31501	HCW 24-53	PA

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Removal Confirmation](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 416866 Type: WELL API Number: 123-31497 Status: PR Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Wells (HCW 24-13, 24-23, 24-53) are plugged and abandoned; cut and cap operations completed. COGCC form 42 notices of start of plugging operations received Sept 2021. The off location wellhead flowlines are being removed (approx 2300' in length/ contractor Mundt on site); on location dump and process flowlines at facility/ battery have been removed (confirmed during inspection and via communications). No flowline risers observed at the (PA) wellhead or facility/ battery (decommissioned/ tanks and equipment removed) areas during this field inspection.

Corrective Action: _____

Date: _____

Facility ID: 416871 Type: WELL API Number: 123-31500 Status: PR Insp. Status: PA

Facility ID: 416872 Type: WELL API Number: 123-31501 Status: TA Insp. Status: PA

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102689	Flowlines removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5573276
690102690	View E from PA wellheads toward battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5573277