

Inspection Photos

API: 071-06703

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/3/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06703 | Date: 11/3/2021

Inspection Photos



Photo 1. Facing northeast along the main access road. Stormwater erosion from this area is causing more erosion further down the road. Lat/Long:37.2354,-104.6646



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06703 | Date: 11/3/2021

Inspection Photos



Photo 2. Facing back southwest. The road side is not stabilized and stormwater runoff is causing erosion further down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06703 | Date: 11/3/2021

Inspection Photos



Photo 3. Facing southwest. Stormwater is flowing across the road at red arrow and is not being diverted toward the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06703 | Date: 11/3/2021

Inspection Photos



Photo 4. There is erosion along the east side of the road which needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06703 | Date: 11/3/2021

Inspection Photos



Photo 5. Facing northeast toward the well site.

