

Inspection Photos

API: 071-08723

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/3/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08723 | Date: 11/3/2021

Inspection Photos



Photo 1. Facing southeast along the access road. There is an erosion gully along the road side. The culvert at red arrow is filled in with sediment and the erosion gully was measured to be 4.5 ft. deep.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08723 | Date: 11/3/2021

Inspection Photos



Photo 2. Facing southeast further down the road. There is erosion along the road that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08723 | Date: 11/3/2021

Inspection Photos



Photo 3. Facing north near the location. There is erosion along the road coming from the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08723 | Date: 11/3/2021

Inspection Photos



Photo 4. Facing north toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08723 | Date: 11/3/2021