

# Inspection Photos

API: 071-06508

API: 071-06734

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/3/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06508 | Date: 11/3/2021

## Inspection Photos



**Photo 1.** There is a metal building along the access road where oil and gas vehicles parked off the designated road way blocking this building. This area has not been restricted to prevent access by fence installation per landowner request.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06508 | Date: 11/3/2021

## Inspection Photos



**Photo 2.** The access road has been regraded however there are steep areas with insufficient gravel and stabilization. The red arrow points to a culvert that was damaged from grading. Lat/Long:37.23640,-104.69944



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06508 | Date: 11/3/2021

## Inspection Photos



**Photo 3.** The culvert was damaged which can puncture a tire. This needs to be repaired. Additionally, the ribbon markers need to be removed once work is completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06508 | Date: 11/3/2021

## Inspection Photos



**Photo 4.** The culverts along the road have been cleaned out and repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06508 | Date: 11/3/2021

## Inspection Photos



**Photo 5.** There are areas along the road that have been seeded and hydromulched. Outlet protection was installed at the culvert and stormwater diversion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06508 | Date: 11/3/2021

## Inspection Photos



**Photo 6.** This steep area of the road was regraded however there is now loose soils shown in photo on the right. This area needs to be stabilized (e.g. gravel, road base).



## Inspection Photos



**Photo 7.** The cattleguard along the road has been repaired. Further up the road another cattle guard was also repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06508 | Date: 11/3/2021

## Inspection Photos



**Photo 8.** Facing west at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06508 | Date: 11/3/2021

## Inspection Photos



**Photo 9.** Facing toward the pit. The pit was scuffed but there is still gray soil that remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06508 | Date: 11/3/2021

## Inspection Photos



**Photo 10.** Facing north at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06508 | Date: 11/3/2021