

TEP RWF 433-10 Location # 335615



location



location

TEP
RWF 433-10
Location # 335615



location



Lack of stabilization/compaction



TEP
RWF 433-10
Location # 335615



Lack of stabilization/compaction



Lack of stabilization/compaction



TEP
RWF 433-10
Location # 335615



Load out line missing cap/bull plug



Load out line missing cap/bull plug



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
RWF 433-10
Location # 335615



Load out line missing cap/bull plug



Load out line missing cap/bull plug



TEP
RWF 433-10
Location # 335615



**Load out line missing cap/bull plug, leaking and
bucket full of fluid**



bucket full of fluid and spilling out

TEP
RWF 433-10
Location # 335615



Unmarked tanks



Unmarked tanks



TEP
RWF 433-10
Location # 335615



Lack of stabilization/erosion



Lack of stabilization/erosion



TEP
RWF 433-10
Location # 335615



Lack of stabilization/erosion



Lack of stabilization/compaction



TEP
RWF 433-10
Location # 335615



Debris



Debris