

TEP
RWF 32-10
Location # 335659



location



location



TEP
RWF 32-10
Location # 335659



location



location

TEP
RWF 32-10
Location # 335659



Erosion on access to wells



Erosion on access to wells



TEP
RWF 32-10
Location # 335659



Sediment trap is full



location



TEP
RWF 32-10
Location # 335659



Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
RWF 32-10
Location # 335659



Erosion/sediment migration behind separators



Erosion/sediment migration behind separators



TEP
RWF 32-10
Location # 335659



Erosion/sediment migration behind separators



Access road drainage crossing needs maintained

TEP
RWF 32-10
Location # 335659



Access road drainage crossing needs maintained



Access road drainage crossing needs maintained



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
RWF 32-10
Location # 335659



Load line missing bull plug/cap



Load line missing bull plug/cap

