

TEP Clough 119 Location # 322434



location



location

TEP
Clough 119
Location # 322434




location



Load line missing bull plug/cap

TEP
Clough 119
Location # 322434



Load line missing bull plug/cap



Lack of stabilization/compaction



TEP
Clough 119
Location # 322434



Lack of stabilization/compaction



Cut slope erosion

TEP
Clough 119
Location # 322434



Berm is failing



Berm is failing

