

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/29/2021

Submitted Date:

11/01/2021

Document Number:

700703458**FIELD INSPECTION FORM**Loc ID 334661 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264018	WELL	PR	08/12/2003	GW	045-08147	GMR 34-12 (N34)	PR
264019	WELL	PR	04/01/2021	GW	045-08172	GMR 34-12A (N34)	PR
264022	WELL	PR	06/18/2002	GW	045-08145	GMR 34-11A1 (N34)	PR

**General Comment:****COGCC Inspection Report Summary**

On Friday 10/29/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus N34, at Location # 334661 in Garfield county Colorado.

While there, I observed well was shut in. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. One horizontal and four vertical unit separators includes 2 glycol storage tank, storage vessel contains no labeling to specify capacity or chemical hazard information.

2. Load line missing cap/bull plug

3. Open ended piping for thawing out dump lines on tanks with exhaust from trucks.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	One horizontal and four vertical unit separators includes 2 glycol storage tank, storage vessel contains no labeling to specify capacity or chemical hazard information.		
Corrective Action:	Install proper labeling	Date:	02/01/2022
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Open ended piping for thawing out dump lines on tanks with exhaust from trucks.		
Corrective Action:	Eliminate possibility of wildlife to enter open lines for thawing out dump lines with exhaust from trucks.	Date:	11/12/2021
Type	OTHER		
Comment:	Load line missing cap/bull plug		
Corrective Action:	Comply with rule 603.i.	Date:	11/12/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Bird Protectors	# 2		corrective date
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities			
Facility ID: 264018	Type: WELL	API Number: 045-08147	Status: PR Insp. Status: PR
<b>Producing Well</b>			
Comment:	Producing		
Corrective Action:		Date:	
Facility ID: 264019	Type: WELL	API Number: 045-08172	Status: PR Insp. Status: PR
<b>Producing Well</b>			
Comment:	Producing		
Corrective Action:		Date:	
Facility ID: 264022	Type: WELL	API Number: 045-08145	Status: PR Insp. Status: PR
<b>Producing Well</b>			
Comment:	Producing		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Ditches						
		Ditches				
		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402858920	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569277">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569277</a>
700703462	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569271">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569271</a>