

Inspection Photos

11/05/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334336

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334336



Photo 1: Photos 1-3 taken from the production areas of the Location. Photos provide examples showing that control measures to stabilize, mitigate tracking and offsite sediment transport at the production areas of the Location are missing or insufficient.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334336



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334336



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334336



Photo 4: Photo taken from the sediment trap on the southwest end of the Location; stormwater discharge from the trap continues into a stormwater diversion ditch that travels southwest of the Location. Photo shows control measure has not been constructed with an appropriate outlet in accordance with good engineering practices.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334336



Photo 5: Photo taken from the stormwater diversion ditch southwest from the Location and the sediment trap; erosion degradation and incising due to stormwater runoff evident within ditch; control measures have not been constructed per good engineering practices or maintained in proper functioning condition



Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334336



Photo 6: Continued from photo 5. Photo shows erosion degradation within the ditch.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334336



November 5, 2021
39.40735103N 107.72532143W

Photo 7: Photo taken southwest of the location, at the point where the stormwater diversion ditch and runoff turns 90 degrees and continues to travel to the northwest. Photos 8-10 show the erosion degradation due to improper stormwater discharge northwest from this position.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334336



Photo 8: Continued from photo 7. Photo shows gully erosion due to inadequate stormwater and erosion control measures, and improper stormwater discharge from the Location.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334336



Photo 9: Photo shows gully erosion due to inadequate stormwater and erosion control measures, and improper stormwater discharge from the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334336



Photo 10: Photo shows gully erosion due to inadequate stormwater and erosion control measures, and improper stormwater discharge from the Location.

