

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2021

Submitted Date:

10/22/2021

Document Number:

689806545

FIELD INSPECTION FORMLoc ID 438250 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------------|--------------|--|-----------------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Inspections, General | | sandridgeenvironmental@san dridgeenergy.com | All Inspections |
| Boyer, David | 303-994-0000 | david@d90energy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 438251 | WELL | DG | 04/10/2017 | LO | 057-06530 | Ray Ranch 0780 4-16H | SI |
| 438252 | WELL | PR | 03/01/2019 | OW | 057-06531 | Ray Ranch 0780 #1-16H | PR |
| 446363 | WELL | PR | 08/01/2020 | OW | 057-06554 | Ray Ranch 0780 2-16H | PR |
| 446364 | WELL | DG | 08/06/2016 | OW | 057-06555 | Ray Ranch 0780 3-16H | SI |

General Comment:

Routine FIU follow up inspection. Follow up to inspection from 3/30/2021 document number 689805591. Form 9 to transfer from Sandridge to D90 received 5/12/2021 document number 402676753, form remains In Process.

Stained soil has been removed.

Emergency contact number has been added to location signs.

Battery and Wellhead signs have been updated to reflect current operator but remain out of compliance with updated sign rules, 605.

Because of this, sign related corrective actions remain outstanding. It is suggested that operator read the comments in this and previous inspections in addition to reading the rules, so that signs can be updated to be in compliance.

LocationOverall Good: ☐

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Well signs must contain: the well name, the API number, and the legal location including the quarter/quarter section. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 05/12/2021 |
| Type | BATTERY | | |
| Comment: | Tank Battery sign must include: operator name, telephone number where operator can be reached at all times, telephone number for local emergency services (911 where available), the public road used to access the site, well name, API numbers, and legal location for all wells associated with battery, location of battery including the quarter/quarter section. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 05/12/2021 |

Emergency Contact Number:

Comment: 303-638-6096

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|-------------------------------|-----------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Horizontal Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # | | |
| Comment: | Generator | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 438251 Type: WELL API Number: 057-06530 Status: DG Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Last MIT 12/10/2018

Corrective Action: _____ Date: _____

Facility ID: 438252 Type: WELL API Number: 057-06531 Status: PR Insp. Status: PR**Producing Well**

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 446363 Type: WELL API Number: 057-06554 Status: PR Insp. Status: PR**Producing Well**

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 446364 Type: WELL API Number: 057-06555 Status: DG Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Last MIT 12/10/2018

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | | | | | | |
| | | Gravel | | | | |
| Berms | | | | | | |
| Gravel | | | | | | |
| | | Compaction | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402859987 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5570131 |