

Inspection Photos

API: 071-08927

Operator: OGRIS OPERATING LLC

Inspection Date: 11/8/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08927 | Date: 11/8/2021

Inspection Photos



Photo 1. Facing southeast along the access road. The road was regraded and additional gravel was spread along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 11/8/2021

Inspection Photos



Photo 2. Facing southeast further along the access road. The culverts have been maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 11/8/2021

Inspection Photos



Photo 3. Facing south at the location. There is straw blanket installed along the cut slope where erosion was previously occurring. The bare soils on the flat portion were not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 11/8/2021

Inspection Photos



Photo 4. This area next to the pit has bare soils which did not appear to be seeded. This area needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 11/8/2021

Inspection Photos



Photo 5. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 11/8/2021