

Inspection Photos  
Operator: Hilcorp  
API: 067-08319  
Date: 11/3/2021



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the western project area from the northwestern corner facing southward. Seeding and mulch installation is conducted in sparsely vegetated areas. Revegetation is progressing in other portions.





Photo 3. View of the germination quadrat transect facing eastward. Inset shows birdseye view of typical quadrat along transect.





Photo 4. View of Russian thistle debris within the northern project area. Green vegetation is approximately 250 Canada thistles.



Photo 5. View of weeds stuck around well equipment





Photo 6. View of reference area comprised of open grass field.