

Today's Date:	11/10/2021					
Well Name:	BONDAD 33-10 COM 104	Location:	Sec: 01	Twn: 033N	Rng: 010W	UL: I
API Number:	05.067.07403	Footage:	1400' FSL & 1135' FEL			
Operator:	Hilcorp Energy Company	Area/Run/MSO:	01	0101	Bob Percell	
Meter #:	06633052		Pipeline:	HEC		
INC Number:	693903833	Agency:	COGCC	Inspector:	Catherine Roy	
Type of INC:	Written	Photos Required:	Yes	Due Date:	11/25/2021	
Issue of Concern:	<p>On 11/3/2021 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed: -Remove and properly dispose of weed debris by 5/13/2021. Manage weeds (ie: mowing) to prevent debris. Corrective action date is backdated as corrective action from April 2021 inspection is not adequately addressed.</p> <ul style="list-style-type: none"> - Control weeds by 11/25/2021. See below, and attached photos for additional detail. Corrective Action: <p>Dense kochia debris up to 4ft tall observed within the project area. Remove and properly dispose of weed debris. Manage location to prevent weed debris (ie: mowing).</p> <p>Approximately 15 musk thistles observed within the northern revegetation area. Control weeds.</p> <p>Stormwater and erosion controls were assessed during this inspection and active erosion was not observed. These controls are assessed for whether they are functioning at the time of the inspection only. A determination as to whether or not they are adequate for the location over the duration of production is not made. Continue monitoring and managing stormwater and erosion controls to ensure compliance with stormwater regulations.</p>					



Weeds and weed debris removed from location.

