


Axis Exploration LLC, Freund 14-15
005-06370
Inspection #688311560
11/10/2021
Routine Field Inspection

A photograph of an industrial site, likely an oil or gas wellhead. A large, dark metal structure dominates the background. In the foreground, there is a metal frame with a sign attached to it. The sign contains text identifying the operator, a well number, and a location. The ground is covered in gravel. The lighting is bright, suggesting a sunny day.

Axis Exploration, LLC LC 720.370.5540
720.370.5540
FREUND 14 - 15
SW4/SW4 SEC.15 T5S R63W

Colorado Oil and Gas Conservation Commission
39.60923, -104.43321, 5692.3ft, 212°
11/10/2021 12:44:25 PM



Colorado Oil and Gas Conservation Commission
39.60924, -104.43306, 5698.8ft, 259°
11/10/2021 12:44:58 PM



Colorado Oil and Gas Conservation Commission
39.60924, -104.43313, 5685.7ft, 220°
11/10/2021 12:44:46 PM




Colorado Oil and Gas Conservation Commission
39.60953, -104.43534, 5695.5ft, 79°
11/10/2021 12:46:52 PM



Colorado Oil and Gas Conservation Commission
39.60956, -104.43534, 5695.5ft, 79°
11/10/2021 12:46:57 PM



Colorado Oil and Gas Conservation Commission
39.60962, -104.43534, 5692.3ft, 115°
11/10/2021 12:47:10 PM



Colorado Oil and Gas Conservation Commission
39.60962, -104.43533, 5692.3ft, 120°
11/10/2021 12:47:12 PM

AIRS 0051508001

Colorado Oil and Gas Conservation Commission
39.6096, -104.43531, 5689.0ft, 61°
11/10/2021 12:47:39 PM



Colorado Oil and Gas Conservation Commission

39.6096, -104.43531, 5689.0ft, 2°

11/10/2021 12:47:42 PM



Colorado Oil and Gas Conservation Commission
39.6096, -104.4353, 5689.0ft, 300°
11/10/2021 12:47:44 PM



Colorado Oil and Gas Conservation Commission
39.60931, -104.43533, 5698.8ft, 99°
11/10/2021 12:46:30 PM



Colorado Oil and Gas Conservation Commission
39.6094, -104.43531, 5695.5ft, 151°
11/10/2021 12:46:20 PM