

Today's Date:	10/21/2021					
Well Name:	HUBER SPC FEDERAL 2 14	Location:	Sec: 14	Twn: 035N	Rng: 008W	UL: O
API Number:	05.067.07645	Footage:	990 FSL, 1500 FWL			
Operator:	Hilcorp Energy Company	Area/Run/MSO:	01	0100	Charlie Ruybal	
Meter #:			Pipeline:			
INC Number:	693903772	Agency:	COGCC	Inspector:	Catherine Roy	
Type of INC:	Written	Photos Required:	Yes	Due Date:	11/15/2021	
Issue of Concern:	<p>COMMENT: Dense Russian thistle debris observed within and around the edges of the project area. Revegetation is failed throughout the majority of the former well pad where significant portions of the former well pad do not support any desirable portions and sparse desirable vegetation in other portions.</p> <p>-Remove and properly dispose of weed debris by 11/15/2021. Manage weeds to prevent debris and promote desirable vegetation.</p> <p>-Revegetation needs to be conducted across the majority of the project area by 11/15/2021.</p> <p>COMMENT: Erosional rilling and scouring observed on bare and weedy soils within the project area.</p> <p>-Stormwater (BMPs) and erosion controls (ie: ecofiber, straw mulch, etc.) need to be installed and maintained throughout the reclamation process to stabilize revegetating soils and prevent sediment discharge. Corrective action date 11/15/2021.</p> <p>SEE ATTACHED DOCUMENT AND PHOTOS</p>					

Weeds removed from project area.





Reseeding and Erosion control installed.



