

Inspection Photos
Location Name: Alex H Miller #1
Location ID: 318376



Photo 1 Access road Completely overgrown with vegetation.



Photo 2 Access road Completely overgrown with vegetation

Inspection Photos
Location Name: Alex H Miller #1
Location ID: 318376



Photo 3 Access road Completely overgrown with vegetation



Photo 4 Access road Completely overgrown with vegetation

Inspection Photos
Location Name: Alex H Miller #1
Location ID: 318376



Photo 5 Unused equipment Electric panel with no meter



Photo 6 Debris: dead vegetation around well

Inspection Photos
Location Name: Alex H Miller #1
Location ID: 318376



Photo 7 Well head sign is not readable



Photo 8 Flow line valves are in the closed position.

Inspection Photos
Location Name: Alex H Miller #1
Location ID: 318376



Photo 9 flow line header east of well site



Photo 10 Flow line valves east of site. 2" poly line cut

Inspection Photos
Location Name: Alex H Miller #1
Location ID: 318376



Photo 11 Cut flow line riser and spill underneath



Photo 12 Cut flow line and 1" risers with no caps or valve.

Inspection Photos
Location Name: Alex H Miller #1
Location ID: 318376



Photo 13 Spill underneath cut riser.



Photo 14 Flow line riser not LOTO

Inspection Photos
Location Name: Alex H Miller #1
Location ID: 318376



Photo 15 some type of cellar or hole on location or pipeline right a way



Photo 16 some type of cellar or hole on location or pipeline right a way

Inspection Photos
Location Name: Alex H Miller #1
Location ID: 318376



Photo 17 Debris Dead vegetation on location.