

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021




Photo # - 1



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 2



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 3

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 4

Inadequate secondary containment around skim tank, erosion on east side



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 5

Inadequate secondary containment around skim tank



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 6

Erosion indicates where spilled fluids would be released



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 7

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 8



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo # - 9

Wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 10

Oily soil from oil spray in motor house



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 11

Oily soil from oil spray in motor house



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 12

Oily soil from oil spray in motor house



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 13

Oily soil from oil spray in motor house and/or lube oil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 14

Oily soil from oil spray in motor house



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 16

Oily soil from leaking lube oil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 16

Oily soil from leaking stuffing box



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Western Operating – Roper E-1X Tank Battery
Inspection Date: 11/09/2021



Photo # - 17

Chemical drum extends outside secondary containment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources