

Inspection Photos
Operator: Simcoe
API: 067-07753
Date: 11/11/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass, sand dropseed, smooth brome, intermediate wheatgrass, and crested wheatgrass.



Photo 3. View of bare soils and erosional channels (approx. 10-12 inches wide and deep) on the well pad cut-slopes. .



Photo 4. View of erosional channels and sediment transport occurring on the access road where and erosional channel flows down the well pad entrance and is eroding and discharging material down-slope from the project area. Erosion is approximately 1.5ft wide and up to 12 inches deep.



Photo 5. View of the reference area comprised of ponderosa pine, and pinyon and juniper woodland, with and understory of gambel oak, mountain mahogany, western wheatgrass, muttongrass, and threadleaf sunflower.