

Inspection Photos

API: 071-07791

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07791 | Date: 11/12/2021

Inspection Photos



Photo 2. The culvert along the access road is filled in with sediment causing erosion down the road side. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 11/12/2021

Inspection Photos



Photo 2. There is erosion along the road side which has not been repaired. Red arrow points to 4.5 ft. shovel for scale.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 11/12/2021

Inspection Photos



Photo 3. Facing northeast along the access road. The road is not recontoured and rocks have fallen onto the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 11/12/2021

Inspection Photos



Photo 4. Facing northeast along the access road. The culvert is filled in with sediment shown at red arrow. Rocks have fallen on the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 11/12/2021

Inspection Photos



Photo 5. Facing southeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 11/12/2021

Inspection Photos



Photo 6. Facing east. There is a steep cut slope at the end of the access road that is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 11/12/2021

Inspection Photos



Photo 7. Facing east toward the location. The location has been recontoured and reclaimed but has not yet reached 80% vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 11/12/2021

Inspection Photos



Photo 8. There are areas of erosion along the reclaimed location that need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 11/12/2021

Inspection Photos



Photo 9. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 11/12/2021