

Inspection Photos
Operator: Logos Operating
API: 067-05515
Date: 11/8/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of project facilities. Debris removed.



Photo 3. View of the partially buried vessel within the project area. Cobble placed around the base is not an adequate BMP. Vessel remains in place, approximately 6 inches above ground level (inset).



Photo 4. View of cobble placement within the low water crossing.



Photo 5. View of the western project area from the southwestern corner facing northward. Soils and vegetation are scoured here.



Photo 6. View of the wellhead and facilities, facing northward. Wood debris removed.



Photo 7. View of reference area comprised of open grass field with western wheatgrass, smooth brome, and scattered sagebrush.