

Inspection Photos
Operator: Logos/Simcoe
API: 067-08138 and 067-08731
Date: 7/29/2021



Photo 1. View of the location from the northwestern corner facing southward. Stormwater flows have washed well pad material off of well pad and deposited down-slope and downstream. Water flow is from right to left here.



Photo 2. View of area where stormwater has washed away well pad material, and deposited wood and plant debris on project facilities.



Photo 3. View of sediment, gravel, cobble well pad material washing downstream to the Florida River (facing downslope).



Photo 4. View of a large volume of well pad material discharging off of the project area into the river and along the banks of the river (facing downstream).



Photo 5. View of more material discharge from well pad along and into the Florida River (facing downslope).



Photo 6. View of erosional scouring and debris deposited within the southeastern project area.



Photo 7. View of Logos well in the eastern project area from the southern edge facing center.



Photo 8. View of impacted vegetation and mud deposited on the well pad.



Photo 9. View of woody debris deposited around facilities.



Photo 10. View of tank overflowing in eastern portion of the project area. Oily material pooled outside of tank. Wood debris deposited within and on top of tank.



Photo 11. Another view of material released from overflowing tank.



Photo 12. View of pooled material outside of tank containment.



Photo 13. View of woody debris around wellhead.