

Caerus Piceance LLC
E13W
Location # 334900/334910



Location



location



Caerus Piceance LLC
E13W
Location # 334900/334910



Location



location/ lack of battery signage

Caerus Piceance LLC
E13W
Location # 334900/334910



Location/ lack of battery signage



location



Caerus Piceance LLC
E13W
Location # 334900/334910



Load lines lacking bull plug



Load lines lacking bull plug

Caerus Piceance LLC
E13W
Location # 334900/334910



Load lines lacking bull plug



Load lines lacking bull plug



Caerus Piceance LLC
E13W
Location # 334900/334910



Lack of stabilization/compaction



Lack of stabilization/compaction

Caerus Piceance LLC
E13W
Location # 334900/334910



Lack of stabilization/compaction



Lack of stabilization/compaction



Caerus Piceance LLC
E13W
Location # 334900/334910



Open ended piping for thawing out dump lines on tanks with exhaust from trucks.



Open ended piping for thawing out dump lines on tanks with exhaust from trucks.

Caerus Piceance LLC
E13W
Location # 334900/334910



Nov 15, 2021 at 1:17:01 PM
+39.448524, -107.732599 ±4.71m
COGCC

Open ended piping for thawing out dump lines on tanks with exhaust from trucks.



Nov 15, 2021 at 1:17:13 PM
+39.448524, -107.732599 ±4.71m
COGCC

Glycol vessel lacking labeling