

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENYEART-67S95W /16NWNW

Location ID: 334761



Photo #5179 from entrance to location.



Photo #5180 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENYEART-67S95W /16NWNW

Location ID: 334761



Photo #5181 from entrance to location.



Photo #5182 No battery sign located at the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENYEART-67S95W /16NWNW

Location ID: 334761



Photo #5183 Flowline heating insulation open ended and not capped.