

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2021

Submitted Date:

11/10/2021

Document Number:

689806591**FIELD INSPECTION FORM**Loc ID 312931 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10677Name of Operator: WOLVERINE RESOURCES LLCAddress: 109 EAST 17TH STREET #430City: CHEYENNE State: WY Zip: 82001**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Reeves, Shane		shane@wolverineresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222882	WELL	SI	08/01/2019	GW	081-06242	BIGHOLE-FED LAND BANK 13-1	SI

General Comment:

Routine FIU follow up inspection. Follow up to inspection from 4/2/2021 document number 689805578, 4/5/2021 document number 689805580, and 6/22/2021 document number 689805932. All corrective actions remain outstanding.

Additional compliance issues discovered during this report:
well is overdue for MIT

Location

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign knocked over.		
Corrective Action:	Immediately install sign to comply with Rule 605.d.	Date:	04/06/2021
Type	TANK LABELS/PLACARDS		
Comment:	Incomplete or missing tank labels.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	02/21/2019

Emergency Contact Number:

Comment: 303-241-5523

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Dried annual weeds on location.		
Corrective Action:	Comply with Rule 606.	Date:	07/02/2020
Type	UNUSED EQUIPMENT		
Comment:	3 - 2" and 2 - 2" steel risers at wellhead and former pump jack base not LOTO or marked for abandonment.		
Corrective Action:	Comply with Rule 606.	Date:	11/21/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	5	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:	Date:	

Inspected FacilitiesFacility ID: 222882 Type: WELL API Number: 081-06242 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 12/10/2021

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosion rills leaving location on southeast side and traveling down through field and into ditch on access road. Sediment controls no longer working and acting as debris. Site and road degradation occurring. Containers on location perimeter stored without secondary containment. Tank battery berm not compacted or lined.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/05/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402867593	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5577110
689806592	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5577106