

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2021

Submitted Date:

11/17/2021

Document Number:

701102217

FIELD INSPECTION FORMLoc ID 314990 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 74290

Name of Operator: RETAMCO OPERATING INC

Address: PO BOX 790

City: RED LODGE State: MT Zip: 59068

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gose, Tom	210-216-0819	tomgose@retamco.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Johnson, Joe	406-446-1568	joejohnson@retamco.com	
Heil, John		john.heil@state.co.us	
Glennon, Joe	406-446-1568	joeglennon@retamco.com	
Thompson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230045	WELL	PR	06/01/2021	GW	103-07704	PHILADELPHIA CREEK 1	PR

General Comment:**COGCC Follow Up Inspection Report Summary**

Follow up to 9/7/2021 inspection # 701101923 and 11/10/2021 inspection # 701102195

Uncorrected action item(s)

- No battery sign at tank battery.

Corrected action item(s)

- Tank capacity has been filled in on tank label.
- Dead weed debris have been cleared from location.
- Tank has been lifted for repair and inspection. Stained materials collected in blue polly drums.

During this inspection the following compliance issues were observed:

- Tank labeled WATER with NFPA diamond RED4 BLUE 2 YELLOW 1, Spilled hydrocarbon fluid on tank berm floor from tank.

Contents posted as "Water" Water is not a proper content name for fluids recovered from down hole of well.

- Tank has been lifted for repair and inspection. Inspect, maintain and repair tanks to comply with rule 609.b.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Tank labeled WATER with NFPA diamond RED4 BLUE 2 YELLOW 1 , Spilled hydrocarbon fluid on tank berm floor from tank. Contents posted as "Water" Water is not a proper content name for fluids recovered from down hole of well.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	02/25/2022
Type	TANK LABELS/PLACARDS		
Comment:	Tank capacity has been filled in on tank label.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign at tank battery.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	12/10/2021

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	1	<100 BBLS	STEEL AST		,
Comment:	Tank has been lifted for repair and inspection.				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 12/18/2021

Paint

Condition	
Other (Content)	
Other (Capacity)	72 bbl

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:	Tank has been lifted for repair and inspection. Stained materials collected in blue polly drums.				
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	230045	Type:	WELL	API Number:	103-07704	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701102221	Inspection 701102217 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583131