

# Interim Reclamation Inspection

November 16, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 331236

Inspection Document #: 697503508

Weld County, CO

NENW Section 22 T2N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DEEPE /14N-27HZ  
Location ID: 331236



**Photo 1.** Google Earth aerial imagery taken 10/7/2012 prior to the Kerr McGee Deep locations. Photo illustrates the access road, which was planned to be used by Kerr McGee after their new locations were built.

Inspection Photos  
Location Name: DEEPE /14N-27HZ  
Location ID: 331236




**Photo 2.** Google Earth aerial imagery taken 6/10/2021 after the Kerr McGee Deep locations were built. Photo illustrates a new access road built by Kerr McGee, which is not what was planned to be used. Kerr McGee was planning to use the previous access route illustrated in the previous photo.















## ACCESS ROAD MAP



**Photo 3.** Kerr McGee aerial imagery of the planned and approved access road to be used. Kerr McGee built new access roads that were not approved.

-  Access Road
-  KMG Gathering Line
-  Duke Pipeline
-  RGSi Pipeline
-  Proposed Flowline
-  Legal Drilling Window
-  Exist Battery Location
-  New Battery Location
-  Proposed Wellhead
-  Bottomhole Location
- Potential Drill Sites**



**Aerial Photo**  
**Sec. 22, 27-2N-67W**  
**Weld County, CO**

Author:  
**Teddy Ruampant**

Edited By: TDE

Last Ed  
**5/13**

**Photo 4.** Kerr McGee legend for the previous Access road map.

Inspection Photos  
Location Name: DEEPE /14N-27HZ  
Location ID: 331236



**Photo 5.** Photo taken from the well location, facing South. Photo illustrates interim reclamation has been performed with the evidence of straw crimped mulch stabilizing the seeded soil.



**Photo 6.** Photo taken from the well location, facing East. See comments under Photo 5.



Inspection Photos  
Location Name: DEEPE /14N-27HZ  
Location ID: 331236



**Photo 7.** Photo taken from the well location, facing North. See comments under Photo 5.



**Photo 8.** Photo taken from the well location, facing Northwest. See comments under Photo 5.