

Caerus Piceance LLC
I2W
Location # 334906



Location



location

Caerus Piceance LLC
I2W
Location # 334906



Glycol vessel lacking labeling/ dimensions



Location/ lack of battery signage



Caerus Piceance LLC
I2W
Location # 334906



Open ended piping for thawing out dump lines on tanks with exhaust from trucks.



Open ended piping for thawing out dump lines on tanks with exhaust from trucks.

Caerus Piceance LLC
I2W
Location # 334906



Lack of stabilization/ compaction



**Lack of stabilization/ compaction/ degradation of
berm**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
I2W
Location # 334906



Lack of stabilization/compaction



Lack of stabilization/compaction



Caerus Piceance LLC
I2W
Location # 334906



Photo from previous inspection.



Photo from follow up inspection.



Caerus Piceance LLC
I2W
Location # 334906



Photo on left is from previous inspection. Photo on right is from follow up inspection.