

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2021

Submitted Date:

11/17/2021

Document Number:

700703548**FIELD INSPECTION FORM**
 Loc ID 334906 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271321	WELL	PR	09/01/2004	GW	045-09861	CEDAR SPRINGS RANCH 2-10D(12W)	PR
271324	WELL	TA	02/04/2019	GW	045-09865	BENZEL 2-16B (I2W)	TA
271327	WELL	SI	12/01/2020	GW	045-09862	CEDAR SPRINGS RANCH 2-15A(12W)	SI
271332	WELL	PR	08/15/2004	GW	045-09866	CEDAR SPRINGS RANCH 2-10A2(12W)	PR
271680	WELL	PR	08/11/2004	GW	045-09933	BENZEL 2-9A (I2W)	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 11/17/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus I2W, at Location # 334906 in Garfield county Colorado.

While there, I observed well was shut in. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

C/A (Pronounced rutting in driveway of tear drop traffic pattern shows lack of stabilization/compaction) from previous inspection document # 692403002 has NOT been completed. Therefore C/A date remains the same (4/1/2021)

During this inspection the following compliance issues were observed:

1. Vertical unit separators includes 1 glycol storage tank, storage vessel contains no labeling to specify capacity or chemical hazard information.
 2. Lack of battery signage
 3. Open ended piping for thawing out dump lines on tanks with exhaust from trucks.
 4. Location shows signs of lack of stabilization/compaction from previous inspection. Therefore C/A date remains the same (4/1/2021)
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	Lack of battery signage			
Corrective Action:	Comply with rule 605.e			Date: 12/17/2021
Type	OTHER			
Comment:	Vertical unit separators includes 1 glycol storage tank, storage vessel contains no labeling to specify capacity or chemical hazard information.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Open ended piping for thawing out dump lines on tanks with exhaust from trucks.			
Corrective Action:	Eliminate possibility of wildlife to enter open lines for thawing out dump lines with exhaust from trucks.			Date: 11/26/2021
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Vertical Heated Separator	# 5			corrective date
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 3			
Comment:				
Corrective Action:				Date:

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	Two well heads not plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected FacilitiesFacility ID: 271321 Type: WELL API Number: 045-09861 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 271324 Type: WELL API Number: 045-09865 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Last MIT done 11/15/2018

Corrective Action:

Date: _____

Facility ID: 271327 Type: WELL API Number: 045-09862 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 11/2020

Corrective Action:

Date: _____

Facility ID: 271332 Type: WELL API Number: 045-09866 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 271680 Type: WELL API Number: 045-09933 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						
Compaction	Fail					

Comment: 4. Location shows signs of lack of stabilization/compaction from previous inspection. Therefore C/A date remains the same (4/1/2021)

Corrective Action: Install or repair required BMPs

Date: 04/01/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703551	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583351