

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402772812

Date Received:

08/06/2021

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Gomez, Jason

jason.gomez@state.co.us

Watzman, Ross

(303) 825-4822

rwatzman@kpk.com

.

303-825-4822

cogcc@kpk.com

Ferrin, Jeremy

jeremy.ferrin@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 693505381

Inspection Date: 08/05/2021

FIR Submit Date: 08/05/2021

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 319977

Location Name: BREDEHOFT-61S67W Number: 6SESW County: ADAMS

Qtrqr: SESW Sec: 6 Twp: 1S Range: 67W Meridian: 6

Latitude: 39.987930 Longitude: -104.934040

FACILITY - API Number: 05-001- -00 Facility ID: 202080

Facility Name: BREDEHOFT Number: 1

Qtrqr: SESW Sec: 6 Twp: 1S Range: 67W Meridian: 6

Latitude: 39.987930 Longitude: -104.934040

CORRECTIVE ACTIONS:

1 ☒ CA# 154558

Corrective Action: Contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.

Date: 08/24/2020

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: KPK was not actively flaring/venting at time of inspection. Gas was being routed from the production separator to the tank system as a result of a dump valve malfunction. During normal operations, gas would remain in separator and be consumed on location.

The dump valve was discovered to be malfunctioning on 8/5/21. A Kimray rebuild kit was installed on 8/5/21 to repair the dump valve and stop gas from being sent to the tank system.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Well site facility has no meter house and no sales line to sale gas

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Knop

Signed: _____

Title: Gen Mangr of Air Quality

Date: 8/6/2021 11:03:58 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

402772812	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files