

APACHE CANYON 18-04V API# 05-071-07405 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 693503479



THE LATERAL ROAD TO LOCATION WAS SURFACE CROWNED TO ESTABLISH SHEET FLOW AND ELIMINATE THE TIRE RUTS.

APACHE CANYON 18-04V API# 05-071-07405 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 693503479



THE EROSION RILL ON THE FILL SLOPE WAS REPAIRED. TURF REINFORCEMENT MATS, ROCK SOCKS AND ARMOR WAS INSTALLED IN THE FLOWLINE FOR EROSION CONTROL.

APACHE CANYON 18-04V API# 05-071-07405 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 17, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 693503479



THE SLOPE INTO PIT WAS SOFTENED. EROSION CONTROL BLANKETS WERE INSTALLED FOR SOIL STABILIZATION. THE SOIL WAS SEEDED BY HAND BROADCAST USING AN APPROVED CPW SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION.



THE VEGETATION THAT HAD ESTABLISHED NEAR SURFACE EQUIPMENT WAS MECHANICALLY REMOVED FOR FIRE SAFETY.