

APACHE CANYON 02-14 API# 05-071-08256– OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 08, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201881



GRAVEL WAS PULLED OFF OF THE EDGE OF THE ROAD BACK ONTO THE ROAD SURFACE. GRAVEL WAS ADDED TO THE LOW AREA OF THE ROAD WHERE WATER WAS PONDING TO ALLOW STORMWATER TO DRAIN OFF OF THE ROAD SURFACE AND FOR STABILIZATION. THE LEASE ROAD WAS CROWNED TO ELIMINATE TIRE RUTS AND CREATE SHEET FLOW.

APACHE CANYON 02-14 API# 05-071-08256– OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 08, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201881



THE WATER TURNOUT WAS DOMINATED EAST OF THE WELL PAAD TO ALLOW STORMWATER TO DRAIN FROM THE ROADWAY SURFACE.

APACHE CANYON 02-14 API# 05-071-08256– OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 15, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201881



MAINTENANCE HAS BEEN PERFORMED ON THE LIQUID RING TO STOP THE OIL LEAK. THE IMPACTED SOIL NEAR THE LIQUID RING SKID WAS REMOVED FROM LOCATION.

APACHE CANYON 02-14 API# 05-071-08256– OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 15, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201881



MAINTENANCE HAS BEEN PERFORMED, THE IMPACTED SOIL NEAR THE LIQUID RING SKID WAS REMOVED AND THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.