

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2021

Submitted Date:

11/23/2021

Document Number:

688801036

FIELD INSPECTION FORMLoc ID 333585 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 7650

Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION

Address: 4900 COLLEGE BLVD

City: FARMINGTON State: NM Zip: 87402

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|------------------------------|---------|
| Krueger, Doug | | dkrueger@sudoe.us | |
| Murray, Richard | | g.richard.murray@state.co.us | |
| Hartman, Laura | | lhartman@blm.gov | NRS |
| Stradling, Zak | (505) 324-5074 | zstradling@bmgdrilling.com | |
| Fischer, Alex | | alex.fischer@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 105202 | PIT | | | | - | LA POSTA CANYON 1 | EI |
| 214518 | WELL | PR | 10/01/2020 | GW | 067-06121 | LA POSTA CANYON 1 | EI |
| 214528 | WELL | PA | 05/14/2020 | GW | 067-06131 | DOROTHY L GOULD 3 | EI |

General Comment:

On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer Drilling Corp. La Posta Canyon #1. For the most recent field inspection report of this facility, please refer to document #674600302. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. A construction crew was removing the PBV and Animas Environmental Services personnel were preparing to collect soil samples from below where the PBV was previously located. This site visit was conducted to observe the work proceeding under REM #20752.

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|--|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | PA marker welded onto casing. PA marker for 067-06131 observed during this inspection. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Location sign located near cut off well head. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sign mounted to fencing around PBV. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Posted on location signs.

Corrective Action:

Date: _____

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Post and wire fencing around PBV. Fencing was being removed at the time of this inspection. | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Telemetry equipment. | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | Facility is being decommissioned and all equipment will be removed. | | |
| Corrective Action: | | Date: | |

| | | |
|--------------------|--|-------|
| Type: Flow Line | # 1 | |
| Comment: | Flowline has been located and marked with pin flags. Flow line abandonment will be by removal. | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 100 BBLs | Open Top | | 37.130781,-107.950983 |
| Comment: | PBV was removed during this site visit. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Wells Served By Facilities Above

| |
|------------|
| API Number |
| 067-06121 |

AirsID

| | |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

| | | | | | | | | | |
|--------------|---------------|-------|------------|-------------|----------|---------|---------|---------------|-----------|
| Facility ID: | <u>105202</u> | Type: | <u>PIT</u> | API Number: | <u>-</u> | Status: | <u></u> | Insp. Status: | <u>EI</u> |
|--------------|---------------|-------|------------|-------------|----------|---------|---------|---------------|-----------|

| | | | | | | | | | |
|--------------|---------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID: | <u>214518</u> | Type: | <u>WELL</u> | API Number: | <u>067-06121</u> | Status: | <u>PR</u> | Insp. Status: | <u>EI</u> |
|--------------|---------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|

| | | | | | | | | | |
|--------------|---------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID: | <u>214528</u> | Type: | <u>WELL</u> | API Number: | <u>067-06131</u> | Status: | <u>PA</u> | Insp. Status: | <u>EI</u> |
|--------------|---------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|

Environmental

Spill/Remediation:

Comment: Well has been PA and equipment is being decommissioned with work proceeding under REM #20752. Pit Facility ID #105202, related to this location, has an unknown status in the COGIS database.

Corrective Action: The operator will submit a Form 27 Site Investigation and Remediation Workplan, per Rule 913.c., for Pit closure.

Date: 12/23/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Type: Lined: Pit ID: 105202 Lat: 37.131307 Long: -107.950831

Reference Point: Other: Length: Width:

Lining:Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date: **COGCC Comments**

| Comment | User | Date |
|--|----------|------------|
| On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer Drilling Corp. La Posta Canyon #1. For the most recent field inspection report of this facility, please refer to document #674600302. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. A construction crew was removing the PBV and Animas Environmental Services personnel were preparing to collect soil samples from below where the PBV was previously located. This site visit was conducted to observe the work proceeding under REM #20752. A PA marker had been welded onto the casing for the La Posta Canyon #1. All equipment was to be removed from the location. The location of flow lines had been marked in preparation of excavation and removal. | hughesjo | 11/23/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 688801037 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588452 |