

# Inspection Photos

11/19/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335538

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 335538



**Photo 1:** Photos provide examples of interim areas on the Location that are not progressing towards 1003 uniform revegetative standards.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 335538



**Photo 2:** Photos provide examples of Noxious weeds (Russian olive) observed established on the western/northern interim areas of the Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 335538



**Photo 3:** Photos taken from the slopes on the east end of the Location; control measures to protect/stabilize slopes missing or insufficient; erosion degradation evident. Areas are bare and exposed; desirable vegetative plant establishment not progressing towards 1003 standards.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 335538



**Photo 4:** Photos provide examples of the cut slopes on the Location; control measures to protect and stabilize the cut slopes remains missing or insufficient per good engineering practices; erosion degradation evident. Note: yellow arrow indicating sediment deposition due to erosion at cut slopes.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 335538



**Photo 5:** Photos provide examples of the cut slopes on the Location; control measures to protect and stabilize the cut slopes remains missing or insufficient per good engineering practices; erosion degradation evident. Note: yellow arrow indicating sediment deposition due to erosion at cut slopes.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 335538



**Photo 6:** Photo shows erosion blankets at cut slopes behind separator equipment. Photo right shows sections of the BMP that has not been maintained in proper functioning condition.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 335538



**Photo 7:** Photo shows stockpiled soils stored on the Location. Control measures to mitigate sediment transport from the soil stockpiles are missing or insufficient.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 335538



**Photo 8:** Photo of well API 045-18287 conductor setting; well has not been drilled; Form 2 permit expired 7/24/2020; no Form 4 to abandon well has been submitted; conductor setting requires plugging.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 335538



**Photo 9:** Photos show unused equipment, or equipment not necessary for production stored on the Location.