

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/18/2021

Submitted Date:

11/22/2021

Document Number:

688801034

FIELD INSPECTION FORM

Loc ID 326359 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	
Walter, Kyle		kwalter@enduringresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216309	WELL	PR	09/01/2020	GW	067-07915	LaPosta 3R	EI

General Comment:

On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources La Posta #3R. For the most recent field inspection report of this facility, please refer to document #693903447. COGCC Western Integrity Inspector Richard Murray was on site during this inspection.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	ASTs labels and placards do not comply with Rule 605.h.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 12/22/2021
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Guard fencing present.		
Corrective Action:			Date:
Equipment:			
Type: Vertical Heated Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Valve can labeled "Flushed & Abandoned".		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical supply panel.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:			Date:

Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	HEATED STEEL AST		37.135295,-107.952548
Comment:	Southernmost AST had thief hatch open during this inspection.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
067-07915		

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 216309 Type: WELL API Number: 067-07915 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Drip pot on load out valve of northern AST.
Rip Rap	In Process					
Compaction	Pass	Gravel	Pass			
Berms	In Process					
Ditches	In Process					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Enduring Resources La Posta #3R. For the most recent field inspection report of this facility, please refer to document #693903447. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. Several storm water BMPs on location have either failed or have been filled in with sediment. The ASTs on location do not have signage and placarding as required by Rule 605.h.	hughesjo	11/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402878413	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5587969
688801035	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5587961