

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402786822

Date Received:
09/14/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766
Name of Operator: ARKOMA OPERATIONS LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Andrew Price</u>	<u>918-965-0044</u>	<u>aprice@arkomaops.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903535
Inspection Date: 08/06/2021 FIR Submit Date: 08/13/2021 FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464
Address: 1001 17TH STREET STE 1160
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 325118

Location Name: CRIGLER MVRD UNIT-N33N8W Number: 21NWSE County: LA PLATA
Qtrqtr: NWSE Sec: 21 Twp: 33N Range: 8W Meridian: N
Latitude: 37.087290 Longitude: -107.719180

FACILITY - API Number: 05-067-00 Facility ID: 214045

Facility Name: CRIGLER MVRD UNIT Number: 1
Qtrqtr: NWSE Sec: 21 Twp: 33N Range: 8W Meridian: N
Latitude: 37.087290 Longitude: -107.719180

CORRECTIVE ACTIONS:

1 CA# 154808

Corrective Action: -Repair or install berms or other secondary containment devices per Rule 603.o. by 9/15/2021. Berms need to be stabilized to prevent erosion. Date: 09/15/2021

Response: CA COMPLETED Date of Completion: 08/25/2021

Operator Comment: Repaired berms for tank containment.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 154809

Corrective Action: -Stormwater (ie: BMPs) and erosion controls (ie: erosion control blanket, hydromulch, etc.) need to be installed to stabilize erosion and prevent sediment discharge from the project area, no later than 9/15/2021. Controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 09/15/2021

Response: CA COMPLETED

Date of Completion: 08/24/2021

Operator
Comment:

Trenched in erosion control logs across the cut slopes, filled in channels and rills, removed silt from the diversion ditches and re built diversion berms. Removed silt from the coble check dams and reestablished the check dams along the access road.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 9/14/2021 8:47:11 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402786822	FIR RESOLUTION SUBMITTED
402810035	Crigler MV GU 1 9-15-21 (693903535) remedial report

Total Attach: 2 Files