

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2021

Submitted Date:

11/23/2021

Document Number:

688801036

FIELD INSPECTION FORMLoc ID 333585 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 7650

Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION

Address: 4900 COLLEGE BLVD

City: FARMINGTON State: NM Zip: 87402

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Krueger, Doug		dkrueger@sudoe.us	
Hartman, Laura		lhartman@blm.gov	NRS
Stradling, Zak	(505) 324-5074	zstradling@bmgsdrilling.com	
Fischer, Alex		alex.fischer@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
105202	PIT				-	LA POSTA CANYON 1	EI
214518	WELL	PR	10/01/2020	GW	067-06121	LA POSTA CANYON 1	EI
214528	WELL	PA	05/14/2020	GW	067-06131	DOROTHY L GOULD 3	EI

General Comment:

On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer Drilling Corp. La Posta Canyon #1. For the most recent field inspection report of this facility, please refer to document #674600302. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. A construction crew was removing the PBV and Animas Environmental Services personnel were preparing to collect soil samples from below where the PBV was previously located. This site visit was conducted to observe the work proceeding under REM #20752.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	PA marker welded onto casing. PA marker for 067-06131 observed during this inspection.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Location sign located near cut off well head.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Sign mounted to fencing around PBV.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	TANK BATTERY			
Comment:	Post and wire fencing around PBV. Fencing was being removed at the time of this inspection.			
Corrective Action:				Date:
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	Telemetry equipment.			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:	Facility is being decommissioned and all equipment will be removed.			
Corrective Action:				Date:
Type: Flow Line	# 1			
Comment:	Flowline has been located and marked with pin flags. Flow line abandonment will be by removal.			

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	Open Top		37.130781,-107.950983	
Comment:	PBV was removed during this site visit.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
067-06121		

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 105202 Type: PIT API Number: - Status: Insp. Status: EIFacility ID: 214518 Type: WELL API Number: 067-06121 Status: PR Insp. Status: EIFacility ID: 214528 Type: WELL API Number: 067-06131 Status: PA Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Well has been PA and equipment is being decommissioned with work proceeding under REM #20752. Pit Facility ID #105202, related to this location, has an unknown status in the COGIS database.

Corrective Action: The operator will submit a Form 27 Site Investigation and Remediation Workplan, per Rule 913.c., for Pit closure.

Date: 12/23/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Type: Lined: Pit ID: 105202 Lat: 37.131307 Long: -107.950831

Reference Point: Other: Length: Width:

Lining:Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer Drilling Corp. La Posta Canyon #1. For the most recent field inspection report of this facility, please refer to document #674600302. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. A construction crew was removing the PBV and Animas Environmental Services personnel were preparing to collect soil samples from below where the PBV was previously located. This site visit was conducted to observe the work proceeding under REM #20752. A PA marker had been welded onto the casing for the La Posta Canyon#1. All equipment was to be removed from the location. The location of flow lines had been marked in preparation of excavation and removal.	hughesjo	11/23/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402878932	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588467
688801037	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588452