

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2021

Submitted Date:

11/23/2021

Document Number:

688801040

FIELD INSPECTION FORMLoc ID 325307 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 7650

Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION

Address: 4900 COLLEGE BLVD

City: FARMINGTON State: NM Zip: 87402

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Stradling, Zak	(505) 324-5074	zstradling@bmgdrilling.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
105205	PIT				-	LA POSTA CANYON 2	EI
214532	WELL	PR	10/01/2020	GW	067-06135	LA POSTA CANYON 2	EI

General Comment:

On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer La Posta Canyon #2. For the most recent field inspection report of this facility, please refer to document #693903439. COGCC Western Integrity Inspector Richard Murray was on site during this inspection.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to meter shack.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	All other production equipment has been moved off of this location.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	HHS has been temporarily moved to the La Posta Canyon #4 location while this well was plugged.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	100 BBLs	Open Top		37.135557,-107.960712
Comment:	PBV has been temporarily moved to La Posta Canyon #4 location.				
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		
Corrective Action:		Date: <input type="text"/>
<u>Venting:</u>		
Yes/No		
Comment:		
Corrective Action:		Date: <input type="text"/>
<u>Flaring:</u>		
Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Inspected Facilities							
Facility ID:	105205	Type:	PIT	API Number: -	Status:	Insp. Status:	EI
Facility ID:	214532	Type:	WELL	API Number: 067-06135	Status: PR	Insp. Status:	EI

Environmental

Spill/Remediation:

Comment: Work proceeding under REM #20750 to plug well and decommission location. Pit Facility ID #105205, related to this facility, has an unknown status in the COGIS database.

Corrective Action: The operator will submit a Form 27 Site Investigation and Remediation Workplan for closure of Pit Facility ID #105205.

Date: 12/23/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: _____

Corrective Action: _____

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 105205 Lat: 37.134867 Long: -107.959861

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: _____

Corrective Action _____

Date: _____

COGCC Comments

Comment	User	Date
On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Benson-Montin-Greer La Posta Canyon #2. For the most recent field inspection report of this facility, please refer to document #693903439. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. The La Posta Canyon #2 well head has been cut off and a PA marker has been welded onto the casing. An unmarked AST and a tubing trailer were on site during this inspection. The PBV and separator have been moved to the La Posta Canyon #4 location to allow room for the plugging rig.	hughesjo	11/23/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402879180	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588671

688801041	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588658
-----------	-------------------	---

