

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/18/2021

Submitted Date:

11/23/2021

Document Number:

688801044

**FIELD INSPECTION FORM**
 Loc ID 333826 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Jones, Tammy		tajones@hilcorp.com	All inspections
Shorty, Priscilla		pshorty@hilcorp.com	All SW Inspections
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258094	WELL	PR	12/27/2000	GW	067-08322	ARGENTA 33-10 4-3	EI

**General Comment:**

On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Co. Argenta 33-10 #4-3. For the most recent field inspection report of this facility, please refer to document #687904952. COGCC Western Integrity Inspector Richard Murray was on site during this inspection.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Free standing sign near meter shack.			
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:	AST is not compliant with Rule 605.h.			
Corrective Action:	Install sign to comply with Rule 605.h.		Date:	01/24/2022
Emergency Contact Number:				
Comment:	Posted on location sign. Emergency contact number called to report broken regulator on pump jack supply gas. Gas leak was audible from adjacent location.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
Lube Oil	WELLHEAD	<= 1 bbl		
Comment:	Well head and surrounding area are wet and stained.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 12/23/2021
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Guard fencing present.			
Corrective Action:			Date:	
<b>Equipment:</b>				
				corrective date
Type: Prime Mover	# 1			
Comment:	Natural gas powered.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:

Type: Ancillary equipment	# 1		
Comment:	Transfer pump shack.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	HEATED STEEL AST		37.135714,-107.933696
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above****AirsID**

API Number	API Number	AirsID
067-08322		

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	258094	Type:	WELL	API Number:	067-08322	Status:	PR	Insp. Status:	EI

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On November 18, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Co. Argenta 33-10 #4-3. For the most recent field inspection report of this facility, please refer to document #687904952. COGCC Western Integrity Inspector Richard Murray was on site during this inspection. Emergency contact number called to report broken regulator on pump jack supply gas. Gas leak was audible from adjacent location. The AST on location is not compliant with Rule 605.h requirements. The well head and surrounding area are wet and stained.	hughesjo	11/23/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402879290	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588797">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588797</a>
688801045	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588796">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588796</a>