

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2021

Submitted Date:

12/01/2021

Document Number:

689806642**FIELD INSPECTION FORM**Loc ID 313015 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 3975Name of Operator: ARGALI EXPLORATION COMPANYAddress: PO BOX 416City: RANGELY State: CO Zip: 81648**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone | Email                              | Comment |
|------------------|-------|------------------------------------|---------|
| General, Contact |       | argaliexplorationcompany@gmail.com |         |
|                  |       | dnr_cogccengineering@state.co.us   |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 223317      | WELL | SI     | 01/01/2020  | GW         | 081-06681 | FEDERAL 2-25  | SI          |

**General Comment:**

Routine FIU follow up inspection. Follow up to inspection from 8/10/2021 document number 689806203. Signs have been updated.

Compliance issues remaining in this inspection:

no bradenhead access apparent

**Location**Overall Good: ☐**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           | NFPA label faded.    |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment: 970-629-1906

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                                   |   |  |                  |
|-----------------------------------|---|--|------------------|
| Type: Bradenhead                  | #   |  | corrective date  |
| Comment:                          | Bradenhead inaccessible or not visible.   |  |                  |
| Corrective Action:                | Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) |  | Date: 01/25/2021 |
| Type: Horizontal Heated Separator | # 1   |  |                  |
| Comment:                          |   |  |                  |
| Corrective Action:                |   |  | Date:            |

**Tanks and Berms:**

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| PRODUCED WATER     | 1 | 100 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

Inspector Name: Waldron, Emily

|                    |          |                     |                     |             |  |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |
| Earth              | Adequate |                     |                     | Adequate    |  |
| Comment:           |          |                     |                     |             |  |
| Corrective Action: |          |                     |                     | Date:       |  |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |        |       |      |             |           |         |    |               |    |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:  | 223317 | Type: | WELL | API Number: | 081-06681 | Status: | SI | Insp. Status: | SI |
| Idle Well   |        |       |      |             |           |         |    |               |    |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned |        |       |      |             |           |         |    |               |    |
| Reminder: _____   |        |       |      |             |           |         |    |               |    |
| Comment: _____  |        |       |      |             |           |         |    |               |    |
| Corrective Action: _____  |        |       |      |             |           |         |    |               |    |
| Date: _____   |        |       |      |             |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: No stormwater BMPs observed.Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)CDate: 08/23/2021**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 689806643    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5593509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5593509</a> |