

TEP
RMV 16-35
Location # 323890



location



location

TEP
RMV 16-35
Location # 323890



location



Load lines missing bull plugs/caps



TEP
RMV 16-35
Location # 323890



Load lines missing bull plugs/caps



Location lack of stabilization/compaction

TEP
RMV 16-35
Location # 323890




Location lack of stabilization/compaction



Access road



TEP
RMV 16-35
Location # 323890



Access road lacking maintenance



Sediment migration from access road

