

Grand Mesa Operating CO, Dado 2-21  
073-06770

Inspection #688311692

12/2/2021

Routine Field Inspection



Colorado Oil and Gas Conservation Commission

39.42975, -103.55313, 5337.9ft, 51°

12/02/2021 01:14:34 PM




Stuffing box leak.

Colorado Oil and Gas Conservation Commission  
39.42984, -103.55306, 5364.2ft, 54°  
12/02/2021 01:14:47 PM





Colorado Oil and Gas Conservation Commission  
39.42982, -103.55301, 5380.6ft, 351°  
12/02/2021 01:15:04 PM



Colorado Oil and Gas Conservation Commission  
39.42926, -103.55305, 5400.3ft, 353°  
12/02/2021 01:17:01 PM





Interim reclamation

Colorado Oil and Gas Conservation Commission  
39.42965, -103.55309, 5377.3ft, 142°  
12/02/2021 01:15:32 PM



A photograph of a dry, brown field with a line of wind turbines on the horizon under a clear blue sky. The field is covered in sparse, dry grass. In the background, a series of wind turbines are visible against the horizon. The sky is a clear, pale blue.

Interim reclamation

Colorado Oil and Gas Conservation Commission

39.42964, -103.55308, 5377.3ft, 212°

12/02/2021 01:15:34 PM