

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/02/2021

Submitted Date:

12/04/2021

Document Number:

688311692

FIELD INSPECTION FORM

Loc ID 467075 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 35080
Name of Operator: GRAND MESA OPERATING CO
Address: 1700 N WATERFRONT PKWY B600
City: WICHITA State: KS Zip: 67206

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hutton, Neil		nhutton@gmocks.com	Designated Anent
Reilly, Pat	316-265-3000	preilly@gmocks.com	Designated Agent
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467074	WELL	PR	05/12/2021	OW	073-06770	DADO 2-21	PR

General Comment:

Routine Field Inspection
402853545 04 (--OBJ-VENT_FLARE-H2S) -00 Attachment count: 4 IN PROCESS 10/26/2021

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	sign is missing, was on post by laid down rig		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 316-265-3000

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment:

Corrective Action:

Date:

Type PUMP JACK

Comment:

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

1

Comment: 2021 Form 17 is in COGCC database.

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: gas engine

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:		Date:			

Paint

Condition

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 467074 Type: WELL API Number: 073-06770 Status: PR Insp. Status: PR

Producing Well

Comment: pr 10/1/2021 production reported to COGCC database.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/10/2021 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Seeding	Pass					
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688311717	Grand Mesa Dado 2-21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596398