

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2021

Submitted Date:

11/29/2021

Document Number:

699803808

**FIELD INSPECTION FORM**Loc ID 335596 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 11117 RIVER RUN BLVD

City: BAKERSFIELD State: CA Zip: 93311

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

22 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Armstrong, Jon		jarmstrong@bry.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285007	WELL	PR	04/12/2007	GW	045-12348	CHEVRON 18-3D	PR
285008	WELL	PR	03/27/2013	GW	045-12347	CHEVRON 18-4D	PR
285009	WELL	PR	04/04/2007	GW	045-12346	CHEVRON 18-5D	PR
285010	WELL	PR	04/18/2007	GW	045-12345	CHEVRON 18-2D	PR
285011	WELL	PR	04/18/2007	GW	045-12344	CHEVRON 18-1D	PR

**General Comment:****COGCC Inspection Report Summary**

On Monday 11/29/21 at approximately 12:30 hours, I, Inspector Corey De Paolo,  
Conducted a follow up inspection at BERRY PETROLEUM COMPANY LLC CHEVRON K17 696 /,  
Location #335596 in Garfield County Colorado.

Refer to document #699803289 inspection conducted on 6/28/21. All previous corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) Debris by wellheads with a corrective action date of 12/6/21.
- 2) Location lacks stabilization. No form of tracking BMP at entrance to location with a corrective action date of 12/14/21.

-Location is located in a high priority area. All drainages contribute to Parachute creek.

A follow up on this site inspection needs to be conducted to ensure the  
Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

## Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Horizontal separator units include an attached storage tank. Storage tank is approximately 2'x3'x14' with an approximate capacity of 15 barrels. Based on the sight glass the storage tank appears to be full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard. or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemcial tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2200

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris by wellheads.		
Corrective Action:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.	Date:	12/06/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 5		corrective date
------------------	-----	--	-----------------

Comment:		No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		Date:	
Corrective Action:				Date:	
Type: Ancillary equipment		# 1			
Comment:		Chemical tank by wellheads		Date:	
Corrective Action:				Date:	
Type: Bird Protectors		# 3			
Comment:				Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator		# 5			
Comment:				Date:	
Corrective Action:				Date:	
Type: Gas Meter Run		# 5			
Comment:				Date:	
Corrective Action:				Date:	
Type: Plunger Lift		# 5			
Comment:		All wells on plunger lift		Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:		Centralized containment		
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	285007	Type:	WELL	API Number: 045-12348	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	285008	Type:	WELL	API Number: 045-12347	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	285009	Type:	WELL	API Number: 045-12346	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	285010	Type:	WELL	API Number: 045-12345	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	285011	Type:	WELL	API Number: 045-12344	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail					Gravel insufficient
				Material Handling And Spill Prevention		Chemical tank
		Gravel				
Sediment Traps						
		Check Dams				
Compaction	Fail					Location lacks stabilization.
		Ditches				
		Berms				
Ditches						
		Ditches				
Berms						
		Sediment Traps				
		Compaction				
Other	Fail					No form of tracking BMP at entrance to location

Comment: Location lacks stabilization. No form of tracking BMP at entrance to location.Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 12/14/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Housekeeping and Stormwater for corrective actions</a>	depaoloc	11/29/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402882437	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591706">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591706</a>
699803809	Photos for Insp. #699803808	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591699">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5591699</a>