



**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Dead weeds all around TB location amd wellsite		
Corrective Action:	Comply with Rule 606	Date:	11/03/2021

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	gas engine		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	card indicates current calibration		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
					40.170060,-104.856440
Comment:	See related inspection Doc #699303941, 699304080 & 699304390				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 244760 Type: WELL API Number: 123-12555 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 10/07/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 12/7/2021 at approximately 1310 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Follow up to inspection Doc # 699304392.                      Rollie J Vincent A #1 at API #05-123-12555 in Weld County Colorado. While there, I observed a wellsite and tank battery, PR at the time of inspection. During this inspection the following possible compliance issue was observed and is now delinquent:                      606 Houskeeping: Dead weeds all around wellsite and tank battery locations, CA date 11-3-2021.                      See attached photos.                      Location: dry, Weather: clear.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	12/07/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699304623	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5600413">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5600413</a>