

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2021

Submitted Date:

12/09/2021

Document Number:

689806719

**FIELD INSPECTION FORM**Loc ID 441283 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10524

Name of Operator: GRMR OIL &amp; GAS LLC

Address: P.O. BOX 6280

City: BROOMFIELD State: CO Zip: 80021

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone        | Email                        | Comment |
|-----------------|--------------|------------------------------|---------|
| Leone, John     | 406-493-4294 | john.leone@grmroilandgas.com |         |
| Chaps, Alain    | 443-531-8262 | alainchaps@gmail.com         |         |
| Adesoye, Yosoye | 404-723-6547 | yosoye@grmroilandgas.com     |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 441282      | WELL | SI     | 07/01/2020  | OW         | 081-07818 | Myers 19-11HA | PR          |

**General Comment:**Routine FIU inspection. Compliance issue observed:  
no bradenhead access apparent

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 800-801-0453

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                                   |   |       |                 |
|-----------------------------------|---|-------|-----------------|
| <b>Equipment:</b>                 |   |       | corrective date |
| Type: Bird Protectors             | #                                       |       |                 |
| Comment:                          |   |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Horizontal Heated Separator | # 1                                     |       |                 |
| Comment:                          |   |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Deadman # & Marked          | # 4                                     |       |                 |
| Comment:                          |   |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Pump Jack                   | # 1                                     |       |                 |
| Comment:                          |   |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Emission Control Device     | # 1                                     |       |                 |
| Comment:                          |   |       |                 |
| Corrective Action:                |   | Date: |                 |
| Type: Bradenhead                  | # 0                                     |       |                 |
| Comment:                          | Bradenhead inaccessible or not visible. |       |                 |

|                    |   |       |            |
|--------------------|---|-------|------------|
| Corrective Action: | Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) | Date: | 12/20/2021 |
|--------------------|---|-------|------------|

**Tanks and Berms:**

| Contents       | # | Capacity | Type             | Tank ID | SE GPS |
|----------------|---|----------|------------------|---------|--------|
| PRODUCED WATER | 1 | 400 BBLS | HEATED STEEL AST |         | ,      |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate |                     |                     | Adequate    |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

| Contents  | # | Capacity | Type             | Tank ID | SE GPS |
|-----------|---|----------|------------------|---------|--------|
| CRUDE OIL | 3 | 400 BBLS | HEATED STEEL AST |         | ,      |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate |                     |                     | Adequate    |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

**Venting:**

|                    |       |
|--------------------|-------|
| Yes/No             | NO    |
| Comment:           |       |
| Corrective Action: | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 441282         | Type: WELL | API Number: 081-07818 | Status: SI | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    |            |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |
|                  |                 | Compaction              |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 689806720    | Inspection Photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5602673">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5602673</a> |