

Inspection Photos
Location Name: Rea 18U-03 #2
API: 05-067-08701



Rea 18U-03 #2 location photo.



Rea 18U-03 #2 production equipment.

Inspection Photos
Location Name: Rea 18U-03 #2
API: 05-067-08701



Stained gravel near prime mover exhaust.



Secondary containment for lube oil container is almost full.