

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2021

Submitted Date:

12/03/2021

Document Number:

693506018

FIELD INSPECTION FORM

Loc ID 322262 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

5 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Javernick, Jim	(719) 275-3040	javernick1@bresnan.net	All Inspections
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections
Javernick, Salene		salenej@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210082	WELL	PR	06/01/2021	OW	043-40018	SAN ISABEL S1	PR

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at battery. Emergency contact number do not work.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: <u>01/03/2022</u>
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around well head, under PU and Crude oil tank load out line.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.		Date: <u>01/03/2022</u>
Type	OTHER		
Comment:	Mechanical issue: Well head actively leaking at time of inspection.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>12/04/2021</u>
Type	UNUSED EQUIPMENT		
Comment:	Belt guard		
Corrective Action:	Comply with rule 606		Date: <u>01/03/2022</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Cattle panels		
Corrective Action:			Date:
Equipment:			
Type: Prime Mover			# 1
Comment:			Electric motor
Corrective Action:			Date:
Type: Ancillary equipment			# 1
Comment:			Electric panel
Corrective Action:			Date:
Type: Bradenhead			# 0

Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	100 BBLs	STEEL AST		38.293787,-105.104979
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 210082 Type: WELL API Number: 043-40018 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment:

Annual Bradenhead Testing and Reporting 419 C

01/03/2022

Corrective Action:

For all Wells other than coalbed methane Wells, an Operator will perform an annual Bradenhead test and submit the data to the Director on a Form 17 or other Director-approved method.

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday December 3, 2021 at approximately 2:08PM, I, Inspector Randy Silver, conducted an on-site inspection. Location: San Isabel S1 Operator: Javernick oil API#: 043-40018 County: Fremont While there, I observed a producing well site During this inspection the following possible compliance issues were observed Mechanical issue: Rule 608 e Corrective action date of 12-4-22 See video and photo 3 Unused equipment: Rule 606 Corrective action date of 1-3-22 see photo 4 Stained soil: Rule 905 e Corrective action date of 1-3-22 see photos 2,3,4 Well sign: Rule 605e Corrective action date of 1-3-22 Weather conditions: Clear I called Jim javernich at approx 2:220PM informed him the well head was leaking were tubing meet the cap. He stated he knew of the situation and is working with the state on resolving the issue. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	12/03/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402887059	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595998
693506019	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595994