

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2021

Submitted Date:

12/03/2021

Document Number:

696203393

FIELD INSPECTION FORMLoc ID 324288 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1001 17TH STREET #1900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324288	LOCATION	AC			-	CC 0616-21-32 Pad	RI

General Comment:

On 12/1/2021, Reclamation Specialist Trujillo inspected Laramie Energy's CC 0616-21-32 Pad location in Garfield County, Colorado.

This inspection is a followup to #696203342 to document compliance with the following corrective actions:
1002.f: Stormwater

Inspection is also a followup to Resolution #402877391 stating corrective action has been completed.

Refer to the "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696203342 observed that control measures to stabilize the Location, minimize tracking and offsite sediment transport are missing or insufficient. Inspection required Operator to comply with Rule 1002.f by 11/11/2021.

Operator submitted FIRR 402877391 stating CA was completed 11/18/2021.

It was observed in this inspection that Operator installed gravel on select areas of the Location; from the western entrance leading around the well. Control measures to stabilize the entire Location, minimize tracking and offsite sediment transport per good engineering practices remain missing or insufficient.

Corrective action has not been addressed and remains applicable.

Corrective Action: **Comply with Rule 1002.f**

Date: 11/11/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402886681	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595639
696203394	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595634