

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2021

Submitted Date:

12/03/2021

Document Number:

696203399**FIELD INSPECTION FORM**Loc ID 335815 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1001 17TH STREET #1900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335815	LOCATION	AC			-	Cascade Creek 697-08-53	RI

General Comment:

On 12/1/2021, Reclamation Specialist Trujillo inspected Laramie Energy's Cascade Creek 697-08-53 location in Garfield County, Colorado.

This inspection is a followup to #696203336 to document compliance with the following corrective actions:
1002.f: Stormwater

Inspection is also a followup to Resolution #402870286 stating corrective action has been completed.

Refer to the "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696203336 observed that control measures to stabilize the production area, and minimize tracking and offsite sediment transport are missing or insufficient. Inspection required Operator to comply with Rule 1002.f by 11/11/2021. Operator submitted FIRIR 402870286 stating CA was addressed on 11/10/2021

It was observed that Operator placed gravel on select sections of the Location; along portions of the access road and Location entrance towards wells. Control measures to stabilize the entire Location, minimize tracking and offsite sediment transport per good engineering practices remain missing or insufficient.

Corrective action has not been addressed and remains applicable.

Corrective Action: **Comply with Rule 1002.f**

Date: 11/11/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402886683	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595641
696203400	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595637